








Терморезисторы дисковые

СТ1-2	82; 91; 100; 110 Ом	±5	700	–60...85	4,4...4,9	3800...4200	60...100	Температурная компенсация, измерение и регулирование температуры	
СТ4-2	2,1 кОм...3,0 кОм	–	–	–60...125	4,2...4,8	3170...4120	–	Измерение темпе- ратуры автотрак- торных двигателей	
СТ4-15	880 Ом...1,12 кОм	–	–	–60...155	3,4...3,8		–		
KMT-8	100 Ом...10 кОм	±10;±20	600	–60...70	4,2...8,4	3600...7200	900	Температурная компенсация	
MMT-8	1 Ом...1 кОм	±10;±20	600	–60...70	2,4...4	2060...3430	900		
MMT-9	10 Ом...4,7 кОм	±10;±20	900	–60...125	2,4...5	2060...4300	–		
KMT-12	100 Ом...10 кОм	±30	700	–60...125	4,2...8,4	3600...7200	–	Измерение и регули- рование температуры, температурная компенсация	
MMT-12	4,7 Ом...1 кОм	±30	700	–60...125	2,4...4	2060...3430			
MMT-13	10 Ом...2,2 кОм	±20	600	–60...125	2,4...5	2060...4300	100		
KMT-17В	330 Ом...22 кОм	±10;±20	300	–60...155	4,2...7	3600...6000	30		
СТ1-17	300 Ом...22 кОм	±10;±20	300	–60...100	4,2...7	3600...6000	30	Температурная компен-сация, измерение и регулирование температуры	
СТ3-17	33 Ом...330 Ом	±10;±20	300	–60...100	3,0...4,5	2580...3860	30		
СТ4-17	1,5 кОм...2,2 кОм	±10	500	–80...100	3,8...4,2	3260...3600	30		